

Supplement: 2001 Bethel Church Mitigation Annual Monitoring Report

Stream Monitoring Update – 2001

The stream channel at the Bethel Church Mitigation Site was visually monitored during the annual vegetation monitoring of the site. Due to tree counts that were below the acceptable level, the wetland sections on the south side of US 421 were re-planted in December 2001. During the re-planting, the stream banks were also supplemented with black willow and silky dogwood.

The following photographs show the conditions of the stream as of February 2002. As shown in these photographs, the stream banks have been stabilized with vegetation. In addition naturally re-generating herbaceous vegetation has been established throughout the length of the channel. (Photos 1-3 show portion of stream channel located on northern side of site; Photos 4-6 show portion of stream channel located on southern side of site.)

Bethel Church - Stream



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6